



The Shirpur Education Society's

**R. C. Patel College of Engineering and
Polytechnic, Shirpur**

Department of Mechanical Engineering

NAME OF COURSE: - Production Drawing

CODE OF COURSE: - 313311

SEMESTER: - ME-3K (SYME)

**Unit - 3 Production Drawing
16 Marks**

SUBJECT TEACHER

Mr. Anil S. Patil

Production Drawing - (313311) (PDR)

Unit 3 - Production Drawing

Limit, Fits & Tolerances -

In production process, it is impossible to manufacture an object/part precisely as given dimensions.

Factors affecting -

- i) Man
- ii) Machine
- iii) Material
- iv) Environment
- v) Electricity.

If an object/part is mfg. precisely with perfect size, it will increase the cost of production.

So, it is important to allow some variable permissible variation in ~~manu~~ manufacturing.

3.1 Limits

Defⁿ - Limits are two extreme permissible sizes, between which actual size of an object/part must lie.

Types of Limits =

- i) Upper Limit - Maximum dimension of part.
- ii) Lower Limit - Minimum dimension of part.

ISO system of tolerance - Tolerance

Defⁿ - The permissible variation in size or dimension is known as tolerance.

Tolerance zone -

The difference between upper & lower limit is known as tolerance zone.


Tolerance zone = Upper limit - Lower limit

Types of tolerance -

i) Unilateral tolerance , ii) Bilateral tolerance.

Dimensional tolerances =

Terminology:-



→ Shaft - External dimension of a component.

→ Hole - Internal dimension of a component.

Note - Any assembly is formed by shaft & hole.

→ Basic size (Nominal size) - It is the standard size of a part with reference to which the limits (UL & LL) are derived.

(Basic size is same for shaft & hole)

→ Actual size - Dimension of part measured with measuring instrument.

→ Zero line - A line drawn to represent basic size. (Drawn as center line)

→ Upper deviation - It is difference between the upper limit (UL) of part and basic size.


→ Lower deviation - It is difference between the lower limit (LL) of part and basic size.

→ Fundamental deviation - This is one of the deviation from upper or lower deviation which is nearest to basic size line.

→ Basic shaft - Shaft whose upper deviation is zero.

→ Basic hole - Hole whose lower deviation is zero.

→ Maximum metal limit (MML)



The limit that contains maximum possible amount of metal known as MML.

For shaft - MML is with upper limit

For hole - MML is with lower limit

→ Minimum metal limit (LML)
Least


The limit that contains minimum possible amount of metal called as Least metal limit.

For shaft - LML is with lower limit

For hole - LML is with upper limit

Unilateral & Bilateral tolerance system.

- Unilateral tolerance - In this system, the dimension of a part is allowed to vary in only one side of basic size line (zero line).




Eg. $25^{+0.02}_{+0.01}$ $29^{+0.04}_{+0.02}$ $35^{-0.02}_{-0.04}$ etc

In this system both upper limit & lower limit of a part lie in one side (above or below) the basic size line.

Bilateral tolerance -

In this system of tolerance, both the dimension of part is allowed to vary on both sides of basic size.




In this system, upper limit or lower limit can be lie in opposite to each other to the basic size line.

Fit's

Defⁿ - The degree of tightness or looseness between two mating parts (shaft & hole) to perform a definite function is known as fit.

Types of fits -


- i) Clearance fit
- ii) Transition fit
- iii) Interference fit.



Clearance fit -

In this fit the dimension of shaft is always smaller than the hole.

So, the shaft can rotate, slide, make movements. Eg- Bearing, Piston-cylinder, etc.



Clearance fit exist when the shaft and hole are made with maximum metal condition as shown in above dia.


Types of clearance fit -

- i) Slide fit, ii) Easy slide fit, iii) Running fit,
- iv) Slack running fit, v) Loose running fit.

Interference fit -

In this type of fit minimum allowable diameter of shaft is larger than the maximum permissible diameter of the hole.

The hole & shaft are intended to be attached permanently. No relative motion between hole & shaft.




Types of interference fit -

Transition fit -

This fit is a midway between clearance & interference fit.

In this type the limits of hole & shaft are so selected that either interference or clearance may occur.

Tolerance zones of hole & shaft are overlap in part.



Types of transition fit -

- i) Wringing fit, ii) Push fit

#


Allowance -

Allowance is intentional difference between dimensions of two mating parts for getting type of fit.

The difference between lower limit of hole & higher limit of shaft

Positive allowance - Clearance

Negative allowance - Interference.




System to obtain different types of fits -

i) Hole basis system, ii) Shaft basis system

i) Hole basis system -

In this system, dimension of hole kept constant while the dimension of hole ~~is~~ shaft is varied to obtain required type of fit.




The lower deviation of hole is zero.
i.e. Lower limit of hole is taken as basic size.

The upper limit of hole, ϕ Upper limit of shaft & lower limit of shaft is then varied to obtain desired fit. (View fig)

ii) Shaft basis system -

In this system, dimension of shaft is kept constant while the dimension of hole is varied to obtain required type of fit.



The upper deviation of shaft is zero.
i.e. upper limit of shaft is taken as basic size

The lower limit of shaft, upper & lower limit of hole is then varied to obtain desired output.

Selection of fit for engineering applications -

i) Application -

- a) Free rotation required - Clearance fit
eg. shaft in bearing.
- b) Fixed connection required - Interference fit
eg. screwed joint.
- c) Connection with low mfg. cost - Transition fit
eg. Nut-bolt assembly.

ii) Load & stress requirement.

- a) Minimal loading - Clearance fit
- b) For high load & torque - Interference fit
- c) Accurate location with some load → Transition fit

iii) Material - Interference fit can handle high stresses, ~~so as per type of fit~~ - as compared with clearance & transition fit. So, proper selection of material needed.

iv) Cost & time requirement.

It is very difficult to obtain either clearance or interference fit. So, transition fit is less time consuming & also low cost solution to above problem.

Simple numericals for calculating type of fit -

i) The shaft size is $\phi 27.470$ mm & $\phi 27.445$ mm. Hole size is $\phi 27.5$ mm & $\phi 27.523$ mm. Determine type of fit.

→ For hole -

$$UL \text{ of hole} = 27.5 \text{ mm}$$

$$LL \text{ of hole} = 27.523 \text{ mm}$$

$$UL \text{ of shaft} = 27.470 \text{ mm}$$

$$\begin{aligned} \text{Maxi. allowance} &= \text{UL of hole} - \text{LL of shaft} \\ &= 27.5 - 27.425 \\ &= 0.075 \text{ (+ve)} \end{aligned}$$

$$\begin{aligned} \text{Min. allowance} &= \text{LL of hole} - \text{UL of shaft} \\ &= 27.523 - 27.470 \\ &= 0.053 \text{ (+ve)} \end{aligned}$$

As max & min allowance has +ve values so the type of fit is clearance fit.

2) The shaft has $\phi 9^{-0.025}$ & hole is $\phi 9^{+0.022}$
Determine type of fit.

$$\rightarrow \text{UL of hole} = 9 + 0.022 = 9.022 \text{ mm}$$

$$\text{LL of hole} = 9 + 0 = 9 \text{ mm}$$

$$\text{UL of shaft} = 9 - 0.025 = 8.975 \text{ mm}$$

$$\text{LL of shaft} = 9 - 0.047 = 8.953 \text{ mm}$$

$$\begin{aligned} \text{Maxi allowance} &= \text{UL of hole} - \text{LL of shaft} \\ &= 9.022 - 8.953 \\ &= 0.069 \text{ (+ve)} \end{aligned}$$

$$\begin{aligned} \text{Min allowance} &= \text{LL of hole} - \text{UL of shaft} \\ &= 9 - 8.975 \\ &= 0.025 \text{ (+ve)} \end{aligned}$$

Type of fit is clearance fit. (Both maxi & min allowance is +ve).

3) The hole has $\phi 16^{+0.023}$ & shaft has $\phi 16^{-0.012}$
Determine type of fit.

$$\rightarrow \text{UL of hole} = 16 + 0.018 = 16.018 \text{ mm}$$

$$\text{LL of hole} = 16 - 0 = 16 \text{ mm}$$

$$\text{UL of shaft} = 16 + 0.023 = 16.023 \text{ mm}$$

$$\text{LL of shaft} = 16 - 0.012 = 15.988 \text{ mm}$$

$$\begin{aligned} \text{Maxi allowance} &= \text{UL of hole} - \text{LL of shaft} \\ &= 16.018 - 15.988 \\ &= 0.03 \text{ mm (+ve)} \end{aligned}$$

$$\text{Min allowance} = \text{LL of hole} - \text{UL of shaft}$$

4) The shaft has $\phi 25^{+0.04}_{+0.02}$ & hole has $\phi 25^{-0.02}_{-0.04}$ mm.
 Determine type of fit.

→ UL of hole = $25 - 0.02 = 24.98$ mm

LL of hole = $25 - 0.04 = 24.96$ mm

UL of shaft = $25 + 0.04 = 25.04$ mm

LL of shaft = $25 + 0.02 = 25.02$ mm

Max allowance = UL of hole - LL of shaft
 $= 24.98 - 25.02$

$= -0.04$ mm (-ve)

min allowance = LL of hole - UL of shaft

$= 24.96 - 25.04$

$= -0.08$ mm (-ve)

Type of fit is interference fit.

(Both max & min allowance has -ve)

Selection & representation of dimensional tolerances - (Number & Grade method)

It consist of suitable combination of 18 grades of fundamental tolerances and 25 types of fundamental deviations.

18 grades of fundamental tolerances =

IT01, IT0, IT1 to IT16.

25 Fundamental deviations (Indicated by letter)


A, B, C, D, E, F, G, H, js, J, K, M, N, P, R, S, T, U, V, X, Y, Z, ZA, ZB, ZC. etc.

For shaft a to h → The upper deviation is below zero line & j to z it is above zero line.

For hole A to H → The lower deviation is above zero line & J to Zc it is below zero line. (As attached herewith)

Designation of holes, shafts & fits.

A hole or shaft can be designated by basic size followed by a letter and



- eg. (i) A 40 mm hole, with tolerance grade of IT7 is written as 40 H7. (For hole capital letter is used)
- (ii) A 40 mm shaft, with tolerance grade of IT8 is written as 40 f8. (For shaft lower case of letter is used)
- (iii) A 40 mm ~~hole~~ hole with IT grade ~~IT7~~ IT7 & 40 mm shaft with IT grade f8. The type of fit can be designated by 40 H7 f8.

Numericals

(i) What is the meaning of 25 H7 g8? Determine type of fit.

→ 25 H7 g8

↳ Basic size,

H7 = Hole with tolerance grade IT7.

g8 = shaft with tolerance grade IT8.

Type of fit is clearance fit.

(ii) 50 H7 s6

→ 50 = Basic size

H7 = Hole with tolerance grade IT7

s6 = Shaft with tolerance grade IT6

Type of fit is transition fit

(iii) 30 H7 dg

30 = Basic size

H7 = Hole with IT grade 7

dg = shaft with IT grade 7

Type of fit is clearance


Production Drawing_PDR_(313311)

Unit 3 _ Production Drawing


3.2 Types of geometrical tolerances

Type	Geometrical tolerance	Symbol	Datum needed
Form	Straightness		NO
	Flatness		NO
	Roundness		NO
	Cylindricity		NO
	Profile of a line		NO
	Profile of a surface		NO
Orientation	Parallelism		YES
	Perpendicularity		YES
	Angularity		YES
	Profile of a line		YES
	Profile of a surface		YES
Location	True position		YES or NO
	Coaxiality (concentricity)		YES
	Symmetry		YES
	Profile of a line		YES
	Profile of a surface		YES
Run-out	Run-out		YES
	Total run-out		YES


Terminology for deviation




Q1.



Solution




The radial run out shall not be greater than 0.1 in any plane of measurement during one revolution about the datum axis A - B.




The median plane of the slot shall be contained between two parallel planes which are 0.08 apart and symmetrically disposed about the median plane with respect to the datum feature A.


Q2.



Solution




(X) The toleranced edge is parallel within 0.02 mm to the datum line A.)




(Y) The toleranced edge is perpendicular within 0.033 mm to the datum line A.


Q3.





























Solution



Representation of geometrical tolerance on drawing











3.3 General welding symbols

No.	Designation	Illustration	Symbol
1.	Butt weld between plates with raised edges (the raised edges being melted down completely)		
2.	Square butt weld		
3.	Single-V butt weld		
4.	Single-bevel butt weld		
5.	Single-V butt weld with broad root face		
6.	Single-bevel butt weld with broad root face		
7.	Single-U butt weld (parallel or sloping sides)		
8.	Single-U butt weld		
9.	Backing run; back or backing weld		
10.	Fillet weld		
11.	Plug weld; plug or slot weld		
12.	Spot weld		
13.	Seam weld		

Surface contour and finish of weld

Sl No.	Particulars	Weld Symbol
1	Flush contour	
2	Convex contour	
3	Concave contour	
4	Grinding finish	G
5	Machining finish	M
6	Chipping finish	C















Designation	Illustration	Symbol
Flat (flush) single-V butt weld		
Convex double-V butt weld		
Concave fillet weld		
Flat (flush) single-V butt weld with flat (flush) backing run		

3.4 Machining symbol and surface texture

Roughness grades

R_a micrometer	Roughness Grade Numbers	Finish Marks
50	N12	
25	N11	
12.5	N10	
6.3	N9	
3.2	N8	
1.6	N7	
0.8	N6	
0.4	N5	
0.2	N4	
0.1	N3	
0.05	N2	
0.025	N1	


Indication of machining symbol showing direction of lay

Lay Symbol	Meaning	Example Showing Direction of Tool Marks
	Lay approximately parallel to the line representing the surface to which the symbol is applied.	
	Lay approximately perpendicular to the line representing the surface to which the symbol is applied.	
	Lay angular in both directions to line representing the surface to which the symbol is applied.	
	Lay multidirectional.	
	Lay approximately circular relative to the center of the surface to which the symbol is applied.	
	Lay approximately radial relative to the center of the surface to which the symbol is applied.	
	Lay particulate, non-directional, or protuberant.	

Sampling length

R_a (μm)	R_z (μm)	Sampling length l_r (mm)	Evaluation length l_n (mm)
$(0.006) > R_a \leq 0.02$	$(0.025) > R_z \leq 0.1$	0.08	0.4
$0.02 > R_a \leq 0.1$	$0.1 > R_z \leq 0.5$	0.25	1.25
$0.1 > R_a \leq 2$	$0.5 > R_z \leq 10$	0.8	4
$2 > R_a \leq 10$	$10 > R_z \leq 50$	2.5	12.5
$10 > R_a \leq 80$	$50 > R_z \leq 200$	8	40

Representation of surface roughness on drawing.



QUESTION BANK


Program Name: Mechanical Engineering Program Group	Program Code: ME
Course Title : Production Drawing (313311)	Semester: Third

Unit 3: Production Drawing


1. i) The shaft size $\phi 40^{+0.04}$ and Hole size $+40^{0.000}$. Determine the type of fit between them.
 ii) What is meaning of symbol 'X' and 'Y'.

CO3-3.2-A

W-25



2. Refer given Figure No. 2. (a) and (b) what is meaning of 'X' and 'Y'. CO3-3.2-A



W-25

3. Draw welding symbol of following :- i) Square butt weld ii) Fillet weld iii) Single V-butt weld with broad root face iv) Concave weld.

CO3-3.3-A

W-25

4. The shaft and hole size are given below to find types of fit between them :- CO3-3.1-A

$$\text{Shaft size} = \phi 16^{+0.023}_{-0.012}$$


$$\text{Hole size} = \phi 16^{+0.018}_{-0.000}$$

W-25

5. Give the meaning of following symbol a, b, c, d, e and f Figure No. 3.


CO3-3.4-A

W-25



6. Draw symbol (Tolerance) of following:- CO3-3.2-A **W-25**
 i) Concentricity ii) Perpendicularity iii) Flatness iv) Profile of surface.

7. State the meaning of the symbol shown in Figure No. 1. CO3-3.4-A **W-24, S-25**




8. Draw the symbols for the any two of following: CO3-3.3-A **S-25**
 i) Single V butt weld ii) Seam weld iii) Spot weld iv) Fillet weld with convex finish.

9. Draw the symbols of following features which are controlled in geometrical tolerance.
 i) Symmetry ii) Angularity iii) Concentricity iv) Flatness. CO3-3.2-A **S-25**

10. Two mild steel plates of 8 mm thickness are to be welded to have a lap joint by a fillet weld of leg length 8 mm. Represent the weld on drawing with proper symbol. CO3-3.3-A

11. What is the meaning of symbol at x and y as shown in Figure No. 4. CO3-3.2-A **W-24, S-25**



12. The shaft is given as $\phi 20 \begin{matrix} +0.023 \\ +0.012 \end{matrix}$ and hole size is $\phi 20 \begin{matrix} +0.018 \\ +0.000 \end{matrix}$. Determine the types of fit between them. CO3-3.1-A **S-25**

13. i. Draw a sketch showing basic size, lower deviation, upper deviation and tolerance. (2Marks) CO3-3.1-A **W-24**

- ii. Show machining symbols to represent direction of lay for approximately radial relative to the center of the surface. (2Marks) CO3-3.4-A **W-24**

14. The shaft size is given as $40 \begin{matrix} -0.02 \\ -0.04 \end{matrix}$ and the hole size is $40 \begin{matrix} +0.02 \\ -0.04 \end{matrix}$. Determine the type of fit between them. CO3-3.1-A **W-24**

15. Two rectangular plates are to be welded with each other along the length. The thickness and length of both plates 12 mm and 60 mm respectively. The plates are to be U Butt welded with convex counter. Prepare welding drawing. CO3-3.3-A **W-24**

Handwritten signature: Anil S Patil

Mr A S Patil

Handwritten signature: B. S. Patil

Mr. B. S. Patil